MATERIAL SAFETY DATA SHEET OMNI SPECIALTY PACKAGING

10399 HWY 1 • SHREVEPORT, LA 71115 • (318) 524-1100

Packaged for Stihl Incorporated, 536 Viking Drive, Virginia Beach, VA 23452

MAT	ERIAL	SAF	ETY	DAT	A SH	EET

U.S. DEPARTMENT OF LABOR

May be used to comply OSHA's Hazard Communication Standard 29 CFR 1910.1200.

Occupational Safety and Health Administration. (Non-Mandatory Form)

Standard must be consulted for specific requirements.

Form Approved OMB No.1218-0072.

SECTION I

GENERAL INFORMATION

PRODUCT NAME

STIHL 2-CYCLE ULTRA HIGH PERFORMANCE ENGINE OIL

Product will be packaged in the containers with no less than 25% of post consumer resin.

SECTION II

HAZARDOUS INGREDIENTS/IDENTITY INFORMATION

COMPONENT

WT.% C.A.S. No

Petroleum Distillates, Severely Hydrotreated Heavy Paraffinic

5 - 10 64742-54-7

All mineral oils used in this product have been severely hydrotreated and/or solvent refined. This product does not contain any substances known to the state of California to cause cancer, birth defects or other reproductive harm.

SECTION III

PHYSICAL/CHEMICAL CHARACTERISTICS

Specific Gravity (H ₂ O=1)	0.935	Appearance and Odor	Green liquid with mild petroleum odor
Solubility in Water	Negligible	pН	N/A
Flash Point (PM), ℃	220	Solubility in Solvent	N/A
Pour Point, ℉ (℃)	N/A	%Volatiles By Wt.	N/A
Vapor Pressure (mmHg)	N/A ·	Boiling Point, F°	N/A
Evaporation Rate (Butyl	N/A	Kinematic Viscosity,	49 @ 40℃;
Acetate=1)		cSt	8.45 @ 100°C

SECTION IV

FIRE AND EXPLOSION HAZARD DATA

EXTINGUSHING MEDIA:

Water xx

Foam

XX

CO₂ Xx

Dry Chemicals

XX

Fog SPECIAL FIRE FIGHTING PROCEDURES Wear full-face, self-containing breathing apparatus and impervious protective clothing. Avoid inhaling any combustion products. Direct water spray or foam may cause frothing and spattering. If a leak or spill has not ignited, use water spray to diverse vapors and to flush away from exposure.

UNUSUAL FIRE AND EXPLOSION HAZARDS Non Known.

SECTION V

REACTIVITY DATA

Stable xx Unstable

Corrosive No

Hazardous

Yes

No xx

Incompatibilities:

Polymerization? Strong oxidizing agents.

Hazardous Decomposition or Byproducts:

Decomposition may release oxides of sulfur,

nitrogen, aldehydes, carbon monoxide, carbon dioxide and other low weight hydrocarbons.

Revision Date: 05/08/2006

Page 1 of 3

SECTION VI	HEALTH HAZARD IN	IEODM ATION	
			t Chart Tarm)
OSHA Exposure		m3 (Mist); 10 mg/m3 (Mis	
EYE	Eye irritant.	SKIN	Prolonged or repeated contact may
CONTACT		CONTACT	cause mild irritation and possibly
			dermatitis. Prolonged or repeated
			contact with skin may result in
			allergic skin sensitization reactions.
INHALATION	Lish vaner/several severation	tions INGESTION	
INTALATION	High vapor/aerosol concentra		No significant adverse effects are
	(at elevated temperatures) ca		expected upon ingestion of the
	irritation, headache, dizziness	,	product. If swallowed, can cause
	anesthesia, drowsiness,		nausea, vomiting and diarrhea.
	unconsciousness and death.		Small amounts of this product, if
	Repeated and prolonged		aspirated into the lungs, may cause
	overexposure to oil mists may	result	mild to severe pulmonary injury,
	in droplet deposition, oil grant		possibly death.
	formation, inflammation and		possibly dodni.
•	increased incidence of infection	n .	
	increased incluence of infection	<i>7</i> 11.	•
SECTION VII		IRST AID PROCEDURE	
EYE CONTACT	Flush with water for 15 mir persists.	lutes thoroughly. Get med	lical attention if irritation develops or
SKIN CONTACT	1	hing Wach with coan and	d water. Get medical attention if skin
SKIN CONTAC			
INVESTIGATION	disorder develops. Launde		
INHALATION			mouth resuscitation. Get medical
	attention if symptoms persi		
INGESTION		NG. Consult local poison	control center or get medical
	attention.		
SECTION VIII	SPECIAL PROTECTI	ON INFORMATION	
<u> </u>		ONINFORMATION	
<u> </u>	CONSUMER	BULK HANDLING (Pro	onged Exposure)
RESPIRATORY	CONSUMER	BULK HANDLING (Prol	
	CONSUMER	BULK HANDLING (Prol If mist is generated	(heating, spraying) and engineering
RESPIRATORY	CONSUMER	BULK HANDLING (Prol If mist is generated control are not suffic	(heating, spraying) and engineering ient, wear approved organic vapor
RESPIRATORY PROTECTION	CONSUMER N/A	BULK HANDLING (Prol If mist is generated control are not suffic respirator suitable for oi	(heating, spraying) and engineering ient, wear approved organic vapor
RESPIRATORY	CONSUMER N/A Use with adequate	BULK HANDLING (Prol If mist is generated control are not suffic	(heating, spraying) and engineering ient, wear approved organic vapor
RESPIRATORY PROTECTION VENTILATION	CONSUMER N/A Use with adequate ventilation.	BULK HANDLING (Prol If mist is generated control are not suffic respirator suitable for of General.	(heating, spraying) and engineering ient, wear approved organic vapor I mist.
RESPIRATORY PROTECTION VENTILATION EYE	CONSUMER N/A Use with adequate	BULK HANDLING (Prol If mist is generated control are not suffic respirator suitable for oi	(heating, spraying) and engineering ient, wear approved organic vapor I mist.
RESPIRATORY PROTECTION VENTILATION EYE PROTECTION	CONSUMER N/A Use with adequate ventilation. N/A	BULK HANDLING (Prol If mist is generated control are not suffic respirator suitable for of General. Goggles or full-face ship	(heating, spraying) and engineering ient, wear approved organic vapor I mist.
RESPIRATORY PROTECTION VENTILATION EYE PROTECTION PROTECTIVE	CONSUMER N/A Use with adequate ventilation. N/A Use impervious gloves for	BULK HANDLING (Prol If mist is generated control are not suffic respirator suitable for of General.	(heating, spraying) and engineering ient, wear approved organic vapor I mist.
RESPIRATORY PROTECTION VENTILATION EYE PROTECTION	CONSUMER N/A Use with adequate ventilation. N/A	BULK HANDLING (Prol If mist is generated control are not suffic respirator suitable for of General. Goggles or full-face ship	(heating, spraying) and engineering ient, wear approved organic vapor I mist.
RESPIRATORY PROTECTION VENTILATION EYE PROTECTION PROTECTIVE CLOTHING	CONSUMER N/A Use with adequate ventilation. N/A Use impervious gloves for prolonged contact.	BULK HANDLING (Prol If mist is generated control are not suffic respirator suitable for oi General. Goggles or full-face shie Oil-impervious gloves a	(heating, spraying) and engineering ient, wear approved organic vapor I mist. eld. nd apron.
RESPIRATORY PROTECTION VENTILATION EYE PROTECTION PROTECTIVE CLOTHING SECTION IX	CONSUMER N/A Use with adequate ventilation. N/A Use impervious gloves for prolonged contact. PRECAUTIONS FOR	BULK HANDLING (Prol If mist is generated control are not suffic respirator suitable for oi General. Goggles or full-face shid Oil-impervious gloves a	(heating, spraying) and engineering ient, wear approved organic vapor I mist. eld. nd apron. USE
RESPIRATORY PROTECTION VENTILATION EYE PROTECTION PROTECTIVE CLOTHING SECTION IX SPILL OR LEAK	CONSUMER N/A Use with adequate ventilation. N/A Use impervious gloves for prolonged contact. PRECAUTIONS FOR Remove all sources or	BULK HANDLING (Prol If mist is generated control are not suffic respirator suitable for oi General. Goggles or full-face ship Oil-impervious gloves a SAFE HANDLING AND I ignition. Wear appropria	(heating, spraying) and engineering ient, wear approved organic vapor I mist. eld. nd apron. USE ate protective equipment and clothing
RESPIRATORY PROTECTION VENTILATION EYE PROTECTION PROTECTIVE CLOTHING SECTION IX	CONSUMER N/A Use with adequate ventilation. N/A Use impervious gloves for prolonged contact. PRECAUTIONS FOR Remove all sources of during clean up. Do no	BULK HANDLING (Prol If mist is generated control are not suffic respirator suitable for oi General. Goggles or full-face ship Oil-impervious gloves a SAFE HANDLING AND Inguition. Wear appropriated allow the spilled product.	(heating, spraying) and engineering ient, wear approved organic vapor I mist. eld. nd apron. USE ate protective equipment and clothing of to enter public drainage systems or
RESPIRATORY PROTECTION VENTILATION EYE PROTECTION PROTECTIVE CLOTHING SECTION IX SPILL OR LEAK	CONSUMER N/A Use with adequate ventilation. N/A Use impervious gloves for prolonged contact. PRECAUTIONS FOR Remove all sources of during clean up. Do no open water sources.	BULK HANDLING (Prol If mist is generated control are not suffic respirator suitable for oi General. Goggles or full-face ship Oil-impervious gloves a SAFE HANDLING AND Inguition. Wear appropriated allow the spilled product.	(heating, spraying) and engineering ient, wear approved organic vapor I mist. eld. nd apron. USE
RESPIRATORY PROTECTION VENTILATION EYE PROTECTION PROTECTIVE CLOTHING SECTION IX SPILL OR LEAK PROCEDURE	CONSUMER N/A Use with adequate ventilation. N/A Use impervious gloves for prolonged contact. PRECAUTIONS FOR Remove all sources of during clean up. Do no open water sources. container for disposal.	BULK HANDLING (Prol If mist is generated control are not suffic respirator suitable for oi General. Goggles or full-face shid Oil-impervious gloves a SAFE HANDLING AND fignition. Wear appropriat allow the spilled production of the spilled production o	(heating, spraying) and engineering ient, wear approved organic vapor I mist. eld. nd apron. USE ate protective equipment and clothing of to enter public drainage systems or orbent material and place in closed
RESPIRATORY PROTECTION VENTILATION EYE PROTECTION PROTECTIVE CLOTHING SECTION IX SPILL OR LEAK	CONSUMER N/A Use with adequate ventilation. N/A Use impervious gloves for prolonged contact. PRECAUTIONS FOR Remove all sources of during clean up. Do no open water sources. container for disposal.	BULK HANDLING (Prol If mist is generated control are not suffic respirator suitable for oi General. Goggles or full-face shid Oil-impervious gloves a SAFE HANDLING AND fignition. Wear appropriat allow the spilled production of the spilled production o	(heating, spraying) and engineering ient, wear approved organic vapor I mist. eld. nd apron. USE ate protective equipment and clothing of to enter public drainage systems or orbent material and place in closed
RESPIRATORY PROTECTION VENTILATION EYE PROTECTION PROTECTIVE CLOTHING SECTION IX SPILL OR LEAK PROCEDURE	CONSUMER N/A Use with adequate ventilation. N/A Use impervious gloves for prolonged contact. PRECAUTIONS FOR Remove all sources of during clean up. Do no open water sources. container for disposal.	BULK HANDLING (Prol If mist is generated control are not suffic respirator suitable for oi General. Goggles or full-face shid Oil-impervious gloves a SAFE HANDLING AND fignition. Wear appropriat allow the spilled production of the spilled production o	(heating, spraying) and engineering ient, wear approved organic vapor I mist. eld. nd apron. USE ate protective equipment and clothing of to enter public drainage systems or
RESPIRATORY PROTECTION VENTILATION EYE PROTECTION PROTECTIVE CLOTHING SECTION IX SPILL OR LEAK PROCEDURE WASTE DISPOSMETHOD	Use with adequate ventilation. N/A Use impervious gloves for prolonged contact. PRECAUTIONS FOR Remove all sources or during clean up. Do not open water sources. container for disposal. SAL Dispose in accordance	BULK HANDLING (Prol If mist is generated control are not suffic respirator suitable for oi General. Goggles or full-face shie Oil-impervious gloves a SAFE HANDLING AND fignition. Wear appropriate allow the spilled production of the spilled production	(heating, spraying) and engineering ient, wear approved organic vapor I mist. eld. nd apron. USE ate protective equipment and clothing of to enter public drainage systems or orbent material and place in closed state and federal regulations.
RESPIRATORY PROTECTION VENTILATION EYE PROTECTION PROTECTIVE CLOTHING SECTION IX SPILL OR LEAK PROCEDURE WASTE DISPOSMETHOD STORAGE AND	Use with adequate ventilation. N/A Use impervious gloves for prolonged contact. PRECAUTIONS FOR Remove all sources or during clean up. Do not open water sources. container for disposal. SAL Dispose in accordance	BULK HANDLING (Prol If mist is generated control are not suffic respirator suitable for oi General. Goggles or full-face ship of the control	(heating, spraying) and engineering ient, wear approved organic vapor I mist. eld. dapron. USE ate protective equipment and clothing of to enter public drainage systems or orbent material and place in closed state and federal regulations. ong oxidizing agents. Do not store this
RESPIRATORY PROTECTION VENTILATION EYE PROTECTION PROTECTIVE CLOTHING SECTION IX SPILL OR LEAK PROCEDURE WASTE DISPOSMETHOD STORAGE AND HANDLING	Use with adequate ventilation. N/A Use impervious gloves for prolonged contact. PRECAUTIONS FOR Remove all sources or during clean up. Do not open water sources. container for disposal. SAL Dispose in accordance Store away from heat, material in open or ur	BULK HANDLING (Prol If mist is generated control are not suffic respirator suitable for oi General. Goggles or full-face shie Oil-impervious gloves a SAFE HANDLING AND fignition. Wear appropriate allow the spilled product clean up area with absential applicable local, supparks, open flame or strailabeled containers. "Emplished productions and suitable	(heating, spraying) and engineering ient, wear approved organic vapor I mist. eld. dapron. USE ate protective equipment and clothing of to enter public drainage systems or orbent material and place in closed state and federal regulations. ong oxidizing agents. Do not store this oty" containers retain product residue
RESPIRATORY PROTECTION VENTILATION EYE PROTECTION PROTECTIVE CLOTHING SECTION IX SPILL OR LEAK PROCEDURE WASTE DISPOSMETHOD STORAGE AND	Use with adequate ventilation. N/A Use impervious gloves for prolonged contact. PRECAUTIONS FOR Remove all sources or during clean up. Do not open water sources. container for disposal. SAL Dispose in accordance Store away from heat, material in open or ur (liquid and/or vapor) a	BULK HANDLING (Prol If mist is generated control are not suffic respirator suitable for oi General. Goggles or full-face shie Oil-impervious gloves a SAFE HANDLING AND fignition. Wear appropriate allow the spilled product clean up area with absential applicable local, supported the sparks, open flame or stream and can be dangerous.	(heating, spraying) and engineering ient, wear approved organic vapor I mist. eld. dapron. USE ate protective equipment and clothing of to enter public drainage systems or orbent material and place in closed state and federal regulations. ong oxidizing agents. Do not store this oty" containers retain product residue Do not pressurize, cut, weld, braze,
RESPIRATORY PROTECTION VENTILATION EYE PROTECTION PROTECTIVE CLOTHING SECTION IX SPILL OR LEAK PROCEDURE WASTE DISPOSMETHOD STORAGE AND HANDLING	Use with adequate ventilation. N/A Use impervious gloves for prolonged contact. PRECAUTIONS FOR Remove all sources or during clean up. Do not open water sources. container for disposal. SAL Dispose in accordance Store away from heat, material in open or ur (liquid and/or vapor) a solder, drill, grind, or elements.	BULK HANDLING (Prol If mist is generated control are not suffic respirator suitable for oi General. Goggles or full-face shie Oil-impervious gloves a SAFE HANDLING AND fignition. Wear appropriate allow the spilled product clean up area with absential applicable local, sparks, open flame or strailabeled containers. "Empand can be dangerous. expose used containers to	(heating, spraying) and engineering ient, wear approved organic vapor I mist. eld. dapron. USE ate protective equipment and clothing of to enter public drainage systems or orbent material and place in closed state and federal regulations. ong oxidizing agents. Do not store this oty" containers retain product residue Do not pressurize, cut, weld, braze, o heat, flame, sparks, static electricity,
RESPIRATORY PROTECTION VENTILATION EYE PROTECTION PROTECTIVE CLOTHING SECTION IX SPILL OR LEAK PROCEDURE WASTE DISPOSMETHOD STORAGE AND HANDLING	Use with adequate ventilation. N/A Use impervious gloves for prolonged contact. PRECAUTIONS FOR Remove all sources or during clean up. Do not open water sources. container for disposal. SAL Dispose in accordance Store away from heat, material in open or ur (liquid and/or vapor) a solder, drill, grind, or e or other sources of ig	BULK HANDLING (Prol If mist is generated control are not suffic respirator suitable for oi General. Goggles or full-face shie Oil-impervious gloves a SAFE HANDLING AND fignition. Wear appropriate allow the spilled product clean up area with absential applicable local, supported the spilled production of the spilled containers. "Empand can be dangerous. Expose used containers to spilled; they may explode the spilled production; they may explode the spilled production of the spilled production."	(heating, spraying) and engineering ient, wear approved organic vapor I mist. eld. dapron. USE ate protective equipment and clothing of to enter public drainage systems or orbent material and place in closed state and federal regulations. ong oxidizing agents. Do not store this oty" containers retain product residue Do not pressurize, cut, weld, braze, heat, flame, sparks, static electricity, e. Avoid breathing mists and vapors,
RESPIRATORY PROTECTION VENTILATION EYE PROTECTION PROTECTIVE CLOTHING SECTION IX SPILL OR LEAK PROCEDURE WASTE DISPOSMETHOD STORAGE AND HANDLING	Use with adequate ventilation. N/A Use impervious gloves for prolonged contact. PRECAUTIONS FOR Remove all sources or during clean up. Do not open water sources. container for disposal. SAL Dispose in accordance Store away from heat, material in open or ur (liquid and/or vapor) a solder, drill, grind, or e or other sources of ig prolonged or repeated	BULK HANDLING (Prol If mist is generated control are not suffic respirator suitable for oi General. Goggles or full-face shie Oil-impervious gloves a SAFE HANDLING AND fignition. Wear appropriate allow the spilled product Clean up area with absential applicable local, sparks, open flame or strailabeled containers. "Empand can be dangerous. Expose used containers to inition; they may exploded contact with this material	(heating, spraying) and engineering ient, wear approved organic vapor I mist. eld. dapron. USE ate protective equipment and clothing of to enter public drainage systems or orbent material and place in closed state and federal regulations. ong oxidizing agents. Do not store this oty" containers retain product residue Do not pressurize, cut, weld, braze, o heat, flame, sparks, static electricity, e. Avoid breathing mists and vapors, al. Avoid the generation of oil mists.
RESPIRATORY PROTECTION VENTILATION EYE PROTECTION PROTECTIVE CLOTHING SECTION IX SPILL OR LEAK PROCEDURE WASTE DISPOSMETHOD STORAGE AND HANDLING PRECAUTIONS	Use with adequate ventilation. N/A Use impervious gloves for prolonged contact. PRECAUTIONS FOR Remove all sources or during clean up. Do not open water sources. container for disposal. SAL Dispose in accordance Store away from heat, material in open or ur (liquid and/or vapor) a solder, drill, grind, or e or other sources of ig prolonged or repeated Wash thoroughly after	BULK HANDLING (Prol If mist is generated control are not suffic respirator suitable for oi General. Goggles or full-face shie Oil-impervious gloves a SAFE HANDLING AND fignition. Wear appropriate allow the spilled product Clean up area with absential applicable local, sparks, open flame or strailabeled containers. "Empand can be dangerous. Expose used containers to inition; they may exploded contact with this materi handling. Use this product	(heating, spraying) and engineering ient, wear approved organic vapor I mist. eld. deld. muse ate protective equipment and clothing of to enter public drainage systems or orbent material and place in closed state and federal regulations. ong oxidizing agents. Do not store this oty" containers retain product residue Do not pressurize, cut, weld, braze, o heat, flame, sparks, static electricity, e. Avoid breathing mists and vapors, al. Avoid the generation of oil mists. It with adequate ventilation.
RESPIRATORY PROTECTION VENTILATION EYE PROTECTION PROTECTIVE CLOTHING SECTION IX SPILL OR LEAK PROCEDURE WASTE DISPOSMETHOD STORAGE AND HANDLING	Use with adequate ventilation. N/A Use impervious gloves for prolonged contact. PRECAUTIONS FOR Remove all sources or during clean up. Do not open water sources. container for disposal. SAL Dispose in accordance Store away from heat, material in open or ur (liquid and/or vapor) a solder, drill, grind, or e or other sources of ig prolonged or repeated Wash thoroughly after Keep away from children.	BULK HANDLING (Prol If mist is generated control are not suffic respirator suitable for oi General. Goggles or full-face shie Oil-impervious gloves a SAFE HANDLING AND fignition. Wear appropriate allow the spilled product Clean up area with absential applicable local, sparks, open flame or strailabeled containers. "Empand can be dangerous. Expose used containers to inition; they may exploded contact with this materi handling. Use this producter and animals. Discharger.	(heating, spraying) and engineering ient, wear approved organic vapor I mist. eld. deld. d
RESPIRATORY PROTECTION VENTILATION EYE PROTECTION PROTECTIVE CLOTHING SECTION IX SPILL OR LEAK PROCEDURE WASTE DISPOSMETHOD STORAGE AND HANDLING PRECAUTIONS	Use with adequate ventilation. N/A Use impervious gloves for prolonged contact. PRECAUTIONS FOR Remove all sources or during clean up. Do not open water sources. container for disposal. SAL Dispose in accordance Store away from heat, material in open or ur (liquid and/or vapor) a solder, drill, grind, or e or other sources of ig prolonged or repeated Wash thoroughly after Keep away from children.	BULK HANDLING (Prol If mist is generated control are not suffic respirator suitable for oi General. Goggles or full-face shie Oil-impervious gloves a SAFE HANDLING AND fignition. Wear appropriate allow the spilled product Clean up area with absential applicable local, sparks, open flame or strailabeled containers. "Empand can be dangerous. Expose used containers to inition; they may exploded contact with this materi handling. Use this producter and animals. Discharger.	(heating, spraying) and engineering ient, wear approved organic vapor I mist. eld. deld. muse a proved organic vapor I mist. eld. muse a protective equipment and clothing of the enter public drainage systems or orbent material and place in closed state and federal regulations. ong oxidizing agents. Do not store this oty" containers retain product residue Do not pressurize, cut, weld, braze, or heat, flame, sparks, static electricity, e. Avoid breathing mists and vapors, al. Avoid the generation of oil mists. It with adequate ventilation.

Revision Date: 05/08/2006

424-8802).

SECTION X	OTHER INFORMATION				
NFPA Hazard Rating	- Health - Fire - Reactivity	1 Slight 2 Moderate 0 Least			
Supersedes		OSHA Revised			

While Omni Specialty Packaging believes this data is accurate as of revision date, we make no warranty with respect to the data and we expressly disclaim all liability for reliance thereon. The data is offered solely for your information, investigation, and verification.